

目錄 Table of content

機構設計與特性 Mechanism design and characteristics

主軸單元 Spindle unit

直結式主軸 Direct drive spindle

內藏式高速主軸 Hidden high speed spindle

進給機構設計 Feed mechanism design

工作台與T型槽尺寸 Table and dimension of Tslot

滑道(線性滑軌) Guide-way (linear guide-way)

自動刀具交換系統(ATC) Automatic Tool Changing (ATC) System

搬運及安裝前之準備 Preparation before transport and installation

預防處理 Prevention and handling

安裝環境 Installation environment

安裝環境須知 Installation environment notice

搬運與安裝 Transport and installation

機器安裝 Machine installation

機器的安裝程序 Machine installation procedure

水平調整步驟 Leveling adjustment steps

暫時儲存 Temporary storage

安裝地基 Installation of ground base

安裝後處理 After-installation treatment

RS-232C傳輸及驅動裝置 RS-232C transfer and drive device

試車前之準備 Preparation before pilot run

固定板拆除 Disassembly of retaining plate

機器清潔 Cleaning of machine

機器水平調整 Leveling adjustment of machine

運轉前之檢查 Check before operation

主軸暖機 Warm-up of spindle